

Training Yard Panel

Bulletin 805B: Recommended Spare Parts



Recommended Spare Parts List		
Descriptor	Part Number	Cost
120V Weathertight Horn	FS-350WB-120-30	\$ 235.00
120V Weathertight Beacon	AB-855BS-N10RH4	\$ 410.00
Operator Safety Switch Keys	AB-X-181170	\$ 23.00
Main Disconnect Fuses	PA-DS1001-FU	\$ 55.00
Voltage Transducer Fuses	PA-VT-FU	\$ 21.00
TVSS Cartridge	PX-2905234	\$ 110.00
Operator Pilot Lights	AB-800T-QH2x	\$ 113.00

x Insert lamp color suffix here: "R" Red; "A" Amber; "G" Green; "B" Blue; "W" White