

Training Yard Panel

Bulletin 805B: Recommending Spare Parts



Recommended Spare Parts List		
Descriptor	Part Number	Cost
120V Weathertight Horn	FS-350WB-120-30	\$ 347.11
120V Weathertight Beacon	855BS-N10BL4	\$ 351.41
Operator Safety Switch Keys	AB-X-181170	\$ 51.71
Main Disconnect Fuses	PA-DS1001-FU	\$ 20.95
Voltage Transducer Fuses	PA-VT-FU	\$ 4.88
TVSS Cartridge	PX-2905234	\$ 203.83
Operator Pilot Lights	AB-800T-QH2x*	\$ 65.33

* Insert lamp color suffix here: "R" Red; "A" Amber; "G" Green; "B" Blue; "W" White